we deliver you discover



SCI-PRINT VXL SERVICE PLANS For this instrument, we offer three service plans.



STANDARD PM VISIT

- One scheduled preventative maintenance (PM) inspection per instrument
- Travel expenses related to PM visit
- Performance test
- Thorough cleaning and lubrications of rails and axis
- Functionality testing of sensors, motors, and accessories
- Inspection of fuses, lead-screws, linear bearings & guides, belts, latches, grippers and rollers, hinges, power cords and plugs. (Adjustment, replacement, or repair of these parts done as necessary)

COST: €6.000,00

LEVEL TWO

- One annual preventative maintenance inspection (includes all offerings in Standard PM Visit)
- One on-site service visit for emergency needs.
- Service visit includes repair parts (exclusions apply), labor cost, and travel

LEVEL THREE

- Includes all offerings in Level Two
- One extra on-site service visit for emergency needs.
- Scinomix control software upgrades
- Service visits include repair parts (exclusions apply), labor cost, and travel

COST:

COST: €8.000,00

phone: +33 (0)47 896 4700

web: www.nbsscientific.fr

email: info@nbsscientific.fr





SCI-PRINT VX2 SERVICE PLANS For this instrument, we offer three service plans.



STANDARD PM VISIT

- One scheduled preventative maintenance (PM) inspection per instrument
- Travel expenses related to PM visit
- Performance test
- Thorough cleaning and lubrications of rails and axis
- Functionality testing of sensors, motors, and accessories
- Inspection of fuses, lead-screws, linear bearings & guides, belts, latches, grippers and rollers, hinges, power cords and plugs. (Adjustment, replacement, or repair of these parts done as necessary)

C0ST: €6.000,00

LEVEL TWO

- One annual preventative maintenance inspection (includes all offerings in Standard PM Visit)
- One on-site service visit for emergency needs.
- Service visit includes repair parts (exclusions apply), labor cost, and travel

LEVEL THREE

- Includes all offerings in Level Two
- One extra on-site service visit for emergency needs.
- Scinomix control software upgrades
- Service visits include repair parts (exclusions apply), labor cost, and travel

COST:

email: info@nbsscientific.fr

COST:

€8.000,00

web: www.nbsscientific.fr